



	1008	1108	1210	1215	1310	1610	1615	2012	2517	3020	3030	3525	3535	4040	4545	5050	
<b>Gatmál mm</b>						14	14	14	16								
	10	10	11	11		16	16	16	18	25		35	35	40		70	
	11	11	12	12	14	18	18	18	20	28		38	38	42		75	
	12	12	14	14	16	19	19	19	22	30	35	40	40	45	55	75	
	14	14	16	16	18	20	20	20	24	32	38	42	42	48	60	80	
	15	15	18	18	19	22	22	22	25	35	40	45	45	50	65	85	
	16	16	19	19	20	24	24	24	28	38	42	48	48	55	70	90	
	18	18	20	20	22	25	25	25	30	40	45	50	50	60	75	95	
	19	19	22	22	24	28	28	28	32	42	48	55	55	65	80	100	
	20	20	24	24	25	30	30	30	35	45	50	60	60	70	85	105	
	22	22	25	25	28	32	32	32	38	48	55	65	65	75	90	110	
	24	24	28	28	30	35	35	35	40	50	60	70	70	80	95	115	
	25	25	30	30	32	38	38	38	42	55	65	75	75	85	100	120	
							40	40	40	45	60	70	80	80	90	105	125
							42	42	42	48	65	75	85	85	95	110	
								45	50	70		90	90	100			
								48	55	75							
								50	60								
<b>Boltamál</b>	1/4 x 1/2	1/4 x 1/2	3/8 x 5/8	3/8 x 5/8	3/8 x 5/8	3/8 x 5/8	3/8 x 5/8	7/16 x 7/8	1/2 x 1	5/8 x 1 1/4	5/8 x 1 1/4	1/2 x 1 1/2	1/2 x 1 1/2	5/8 x 1 3/4	3/4 x 2	7/8 x 2 1/4	
<b>Hersla Nm</b>	5.7	5.7	20.0	20.0	20.0	20.0	20.0	31.0	49.0	92.0	92.0	115.0	115.0	172.0	195.0	275.0	
<b>Lengd L</b>	22.3	22.3	25.4	38.1	25.4	25.4	38.1	31.8	43.2	50.8	76.2	63.5	88.9	101.6	114.3	127.0	
<b>Þvermál Dmax</b>	35	38	47.5	47.5	50.5	57	57	70	85.5	108	108	127	127	146	162	177.5	